

**Christian Valley Park CSD
Water Report – April 2022**

Water Plant Operation and Maintenance

1. Average flow for the month 0.252 MGD raw water was 1.5 NTU.

Water Line Repairs and Call Outs

1. 1540 Ellen Ct. – Customer issue.

Miscellaneous

1. Oak Springs Ct – Line replacement – pipe is in and disinfected will be connected soon as it is scheduled.

Capital Improvements

1. None to report

Upcoming Work

1. Filter inspections – pending.
2. Rebuild pump station piping (capital improvement project)

Storage Tank Project Update

1. Need to schedule the 12-month inspection for Tank 2 and repairs for Tank 1.
 - a. Diver quote is sent to Don.